



Airborne Environmental Consultants Ltd

**Fire Risk Assessment  
J182010  
South Liverpool Homes  
6-8A Almeda Road  
Speke  
Liverpool  
L24 7SA**



Approved by

A handwritten signature in black ink, appearing to be "D. Evans".

Darren Evans  
Technical Director

Airborne Environmental Consultants  
23 Wheel Forge Way  
Trafford Park  
Manchester  
M17 1EH  
Tel: 0161 872 7111

## Contents

1 Introduction .....	3
2 Summary .....	4
3 Risk Score .....	5
4 Fire Prevention.....	6
5 Escape Routes & Fire Spread .....	9
6 Detection & Warning .....	11
7 Firefighting .....	12
8 Lighting.....	13
9 Signs & Notices.....	14
10 Fire Management.....	15
11 Action Plan .....	17

## 1 Introduction

The purpose of this fire risk assessment is to provide an informed and structured examination of the potential fire hazards, which could cause harm to those who work in, visit, reside, or try to escape from the above property. As appropriate, it will help decisions to be made on the status of existing fire safety control measures and to ensure compliance with the current fire safety legislation. The observations and recommendations contained in this fire risk assessment are pertinent to the conditions on the date of inspection only.

### Types of survey

The survey which has been undertaken, is a non-destructive type survey (Type 3) in communal areas only, with consideration to exit, doors and means of raising the alarm, and unless there has been any reason to suspect otherwise, the inspection has been purely visual. There may have been a requirement, however, to lift ceiling tiles in communal areas if compartmentation or fire stopping issues were suspected.

### Limitations

The report has been completed on the basis of the scope of works agreed with the client. Therefore, AEC cannot accept responsibility for elements that lie outside the agreed scope. The report is issued to our client in confidence and AEC has no responsibility(s) to any third parties to whom this report may subsequently be circulated in part or in full and any third parties that rely on this report do so at their own risk.

### Disclaimer

The report provides an assessment of the risk to life from fire in these premises, and not building protection issues, and where appropriate, makes recommendations to ensure compliance with fire safety legislation. Whilst the assessor has taken reasonable care to ensure the accuracy of the information provided, the company will not accept liability for any loss (including loss of anticipated profits, loss of expected future business or damage to goodwill) or claim in connection with the information contained within this report.

Airborne Environmental Consultants,  
23 Wheelforge Way,  
Ashburton Point,  
Trafford Park,  
Manchester,  
M17 1EH  
0161 872 7111

## 2 Summary

### The Property

Property address	6-8a Almeda Road, Speke, Liverpool L24 7SA
Number of flat assessed (Type 3)	No access to any flat
Version	1
Assessment date	March 2020
Assessor	Lee Smart BEng (Hons) MCIQB MIFSM
Client	South Liverpool Housing

### Building Information

Property use	Flats Purpose Group 1 (a)
No of floors	2
No of flats	4
Approach to flats	Via protected route
Approximate age and construction details.	The property is of traditional construction, built approximately 1970 and appears to be of masonry construction, concrete floors, concrete stairs and a pitched roof of timber construction overlaid with tile. The internal partitions appear to be a mixture of masonry construction and plasterboard on wooden stud, the internal fire spread of linings on the escape, circulation routes and other areas appears to be Class 0.

### Occupants

Are there any occupants especially at risk from fire?	At the time the audit was carried out the assessor was not made aware of any occupants that may be especially at risk from fire.
-------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------

### 3 Risk Score

Following consideration of current fire safety standards and controls within the premises, the assessor is of the opinion that:

The likelihood of fire occurring is Low  
 The potential severity of harm is Moderate Harm  
 The current risk to life is (Use the table below) Tolerable

		Potential severity of harm		
		Slight Harm	Moderate Harm	Extreme Harm
Likelihood of fire occurring	Low	Trivial	Tolerable	Moderate
	Medium	Tolerable	Moderate	Substantial
	High	Moderate	Substantial	Intolerable

ESTIMATED RISK LEVEL	Action and timescales
Trivial	No further action is required other than maintaining the control measures that are currently in place
Tolerable	No major additional controls required. However there might be a need of improvements.
Moderate	It is essential that efforts be made to reduce the risk. The additional control measures that are recommended should be implemented within a defined time period.
Substantial	Urgent action should be taken to reduce the risk. The additional control measures, that are recommended, should be implemented as soon as possible or limitations should be imposed on the parts of the premises affected.
Intolerable	The premises or the part of the premises affected should not be occupied until the additional control measures that are recommended have been implemented.

## 4 Fire Prevention

### Electrical

---

Are electrical installations and appliances free from any obvious defect? Yes

---

Are fixed installations periodically inspected and tested? See comments

---

Are portable appliances used? No

Comments: Electrical Safety test 14/08/2017

---

### Gas

---

Are gas installations and appliances free from any obvious defect? See comments

---

Is gas equipment protected / located so as not to be prone to accidental damage? See comments

Comments: No gas installations in the communal areas

---

### Heating

---

Are fixed heating installations free from any obvious defect? See comments

---

Are portable heaters used? No

Comments: No heating in communal areas

---

### Cooking

---

---

Does cooking take place on the premises?

See comments

---

Are reasonable measures taken to prevent fires as a result of cooking?

See comments

---

Are filters changed and ductwork cleaned regularly?

See comments

Comments: Yes, but within the individual flats. Cooking is not carried out in the communal areas. The audit was to inspect communal areas and not individual flats as individual flats fall outside the Regulatory Reform (fire safety) Order 2005

---

### Arson

---

Does basic security against arson appear reasonable?

Yes

---

Is there a reasonable absence of external fuels and ignition sources?

Yes

Comments:

---

### Housekeeping

---

Is accumulation of combustibles or waste avoided?

Yes

---

Are there appropriate storage facilities for combustible & hazardous materials?

Yes

Comments: Good level of housekeeping

---

### Hot Works

---

Are there any hot works being carried-out?

No

Comments:

---

### Smoking

---

Are there suitable arrangements taken to prevent fires caused by smoking? Yes

Comments: No evidence of smoking in the communal area.

---

### Dangerous Substances

---

Are dangerous substances present, or liable to be present? No

Comments:

---

### Lightning

---

Is a lightning protection system installed? No

Comments:

---



## 5 Escape Routes & Fire Spread

### Ease of Use

Are exits easily and immediately openable?	Yes
Do fire exits open in direction of escape where necessary?	Yes
Are escape routes unobstructed and safe to use?	Yes
Are there reasonable measures for the evacuation of disabled people?	See comments
Comments: At the time the audit was carried out the assessor was not made aware of any disabled persons in the premises	

### Dimensions

Are travel distances reasonable?	Yes
Is there sufficient exit capacity?	Yes
Comments:	

### Fire Doors

Doors which are expected to be fire resisting:	Electrical cupboards Flat doors Store cupboards
Standard of electrical cupboard doors:	Acceptable
Standard of flat doors:	See action plan
Are fire doors to a suitable standard?	See action plan
Is there suitable provision of self-closing devices?	Yes
Is there suitable provision of hold-open devices?	N/A
	Yes

---

Are doors kept locked where appropriate?

Comments: Door frame has been damaged on store room door. Flat 8 fire door has been damaged.

---

### Construction & Glazing

---

Are escape routes protected with suitable walls and floors?

Yes

---

Is there adequate compartmentation?

See action plan

---

Is the fire stopping in the roof space adequate?

Yes

---

Is there reasonable limitation of linings that might promote fire spread?

Yes

---

Glazing which is expected to be fire resisting, including vision panels and fanlights:

N/A

---

Is glazing reasonable and free from any obvious defects?

N/A

---

Comments: Compartmentation breaches observed in electrical cupboard.

---

### Dampers, Ducts & Chutes

---

Are there suitable measures to restrict fire spread via ducts and concealed spaces?

As this inspection was a type 3 (non-destructive) inspection the assessors cannot verify if there are sufficient cavity barriers or dampers.

---

Comments:

---

### Smoke Ventilation

---

Areas where smoke ventilation is expected:

Staircase

---

Staircase smoke ventilation:

Openable window

---

Is smoke ventilation reasonable and free from any obvious defects?

Yes

---

Comments: Manual opening windows are in the communal areas. These will be used by the fire service for smoke control.

---

## 6 Detection & Warning

Is an electrical fire alarm system expected?	No
Why not?	Purpose built block of flats
Is a fire detection and/or alarm system provided?	See comments
Areas covered	Flats
Comments:	
<ul style="list-style-type: none"><li>• The premises are purpose-built flats and a communal fire alarm system is not required. The flats are designed for a stay put policy.</li><li>• A BS 5839 part 6 fire alarm is installed within the flats</li></ul>	
<a href="#">Flats</a>	
System Category	BS5839 Grade D LD3
Cause & Effect	Sounds alarm in flat of origin
Is the level of false alarms reasonable?	Yes
Is the fire detection & alarm provision reasonable?	Yes
Are there suitable measures for inner rooms?	N/A

## 7 Firefighting

### Fire Extinguishers

---

Are fire extinguishers expected?	No
----------------------------------	----

---

Why not?	No statutory requirement
----------	--------------------------

---

Are fire extinguishers provided?	No
----------------------------------	----

---

Is the provision of fire extinguishers reasonable?	Yes
----------------------------------------------------	-----

---

### Fixed Systems

---

Are any fixed systems provided?	No
---------------------------------	----

---

Is provision of fixed systems reasonable?	Yes
-------------------------------------------	-----

---

### Fire Service Facilities

---

Are there any specific fire service facilities?	No
-------------------------------------------------	----

---

Types of facility	N/A
-------------------	-----

---

Is provision of fire service facilities reasonable?	N/A
-----------------------------------------------------	-----

---

## 8 Lighting

### Normal lighting

---

Is there adequate lighting of internal escape routes?	Yes
-------------------------------------------------------	-----

---

Is there adequate lighting of external escape routes?	Yes
-------------------------------------------------------	-----

---

Is there adequate lighting in risk critical areas?	N/A
----------------------------------------------------	-----

---

### Emergency lighting

---

Method of emergency lighting of internal escape routes:	Non-maintained emergency lighting
---------------------------------------------------------	-----------------------------------

---

Is this provision reasonable?	Yes
-------------------------------	-----

---

---

Method of emergency lighting of external escape routes:	Adequate borrowed lighting
---------------------------------------------------------	----------------------------

---

Is this provision reasonable?	Yes
-------------------------------	-----

---

---

Method of emergency lighting of other areas:	None
----------------------------------------------	------

---

Is this provision reasonable?	Yes
-------------------------------	-----

---

### Comments

---

Comments:
-----------

---

## 9 Signs & Notices

### Escape Routes

Is escape route signage necessary?	No
Why not?	Single escape route
Is escape route signage provided?	No
Is provision of escape route signage suitable?	Yes

### Fire Doors

Is there signage suitable for self-closing fire doors?	Yes
Is there signage suitable for locked fire doors?	Yes
Is there signage suitable for automatic fire doors?	N/A

### Other signs & Notices

Is there suitable signage for fire service facilities?	N/A
Are fire action notices suitable?	Yes
Are there suitable notices for fire extinguishers?	N/A
Is there suitable zone information for the fire alarm system?	N/A

### Comments

Comments:

## 10 Fire Management

### Procedures & Arrangements

Current evacuation policy	Stay put
Are fire action procedures suitable and appropriately documented?	Yes
Are there suitable arrangements for calling the fire service?	Yes
Is there a suitable fire assembly point?	See comments
Are there suitable arrangements for the evacuation of disabled people?	See comments

### Training and Drills

Are staff regularly on the premises?	No
Do staff receive suitable training on the following areas:	
Fire risks on the premises & fire prevention measures?	N/A
Action to take on discovering a fire?	N/A
How to raise an alarm?	N/A
Responding to the fire alarm?	N/A
Calling the fire service?	N/A
Location & use of fire fighting equipment?	N/A
Are fire drills carried out at appropriate intervals?	N/A
Are employees from outside organisations given appropriate fire safety information?	N/A

---

## Comments

Comments: Stay put policy and therefore it is not necessary to have a fixed assembly point. No disabled persons identified. Adaptations will be put into place for any persons that require them.

---

## Testing & Maintenance

---

Is the fire alarm tested & records kept?	See Comments
Is the emergency lighting tested & records kept?	See Comments
Door entry test records	See Comments
Are fire extinguishers subject to suitable tested and records kept?	N/A
Have sprinklers been tested	N/A
Have smoke vents been tested	N/A
Has the Dry Riser been tested	N/A

---


Comments: No fire alarm in communal areas


Emergency lighting	01/10/2019
Door entry system	01/10/2019


---



## 11 Action Plan

Task		
Priority	<b>Medium</b>	
Category	<b>Escape Routes &amp; Fire Spread</b>	
Sub category	<b>Fire Doors</b>	
Significant findings	Store room fire door frame has been damaged. It is unclear if there are ignition sources in there.	
Actions required	Repair door frame to maintain FD30s standard.	
Status	<b>Identified</b>	
Due Date	<b>1st August 2020</b>	

Task		
Priority	<b>Medium</b>	
Category	<b>Escape Routes &amp; Fire Spread</b>	
Sub category	<b>Fire Doors</b>	
Significant findings	Flat 8 fire door frame has been damaged (minor).	
Actions required	Repair door frame to maintain FD30s standard.	
Status	<b>Identified</b>	
Due Date	<b>1st August 2020</b>	

Task		
Priority	<b>High</b>	
Category	<b>Escape Routes &amp; Fire Spread</b>	
Sub category	<b>Construction &amp; Glazing</b>	
Significant findings	Compartmentation breaches observed in the electrical cupboard.	
Actions required	Infill all compartment breaches with suitable fire rated material.	
Status	<b>Identified</b>	
Due Date	<b>1st May 2020</b>	